



Model Communiqué

Executive Series

**Communiqué # 133
November, 2011**

ATA 34 - Announcing Garmin Service Bulletin 1019, Revision B

Hawker Beechcraft Corporation (HBC) recommends that owners/operators of Beechcraft Model G36 (with Garmin G1000 avionics installed) review the Garmin Service Bulletin 1019, Revision B at your earliest opportunity.

This Optional Service Bulletin upgrades both standard and optional components. The G1000 System Software Version 0858.08 and the 9 arc-second Terrain Database SD Card comprise the standard portion of this upgrade and are a prerequisite for the optional upgrades described in this Garmin service bulletin.

A copy of Garmin Service Bulletin 1019, Revision B may be obtained from the Dealer Resource Center portion of the Garmin website www.garmin.com.

Note:

Hawker Beechcraft Corporation assumes no responsibility for providing revisions or changes to this or any supplier information.



SOFTWARE SERVICE BULLETIN

NO.: 1019 Revision B

TO: All Garmin Aviation Service Centers
DATE: October 27, 2011
SUBJECT: Optional G1000 system upgrade for G1000 WAAS-equipped Hawker Beechcraft G36 Bonanza aircraft to System Software Version 0858.08. This upgrade also allows the installation of specific hardware and software options to aircraft already equipped with SW Version 0858.08.
Revision B: Updated bulletin for SW Version 0858.08

PURPOSE

This Service Bulletin provides instructions for implementing STC #SA01595WI-D Garmin G1000 System Software upgrade to v0858.08 for G1000 WAAS-equipped Hawker Beechcraft G36 Bonanza aircraft.

DESCRIPTION

This optional system upgrade consists of both standard and optional components. The G1000 System Software Version 0858.08 and the 9 arc-second Terrain Database SD Card comprise the standard portion of this upgrade and are prerequisite for the optional upgrades described in this service bulletin.

The standard components of this service bulletin add the following features to the G1000 system:

- Airport Directory Feature
- CDI stays on for 20 minutes in dead-reckoning mode (enroute/oceanic phases)
- Database Crossfill Feature
- Datalogging to SD Card
- Flight Plan Import/Export to SD Card
- High-resolution Terrain Database (improves terrain depiction and TAWS-B functionality)
- New XM Weather Products available (AIREPS, PIREPs, icing, turbulence, and NEXRAD coverage in Canada)
- Profile View

© Copyright 2011
Garmin Ltd. or its subsidiaries
All Rights Reserved

Except as expressly provided herein, no part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this document and of any revision to this document onto a hard drive or other electronic storage medium to be viewed and to print one copy of this document or of any revision hereto, provided that such electronic or printed copy of this document or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this document or any revision hereto is strictly prohibited.

ATA 34 - Announcing Garmin Service Bulletin 1132, Revision A

Hawker Beechcraft Corporation (HBC) recommends that owners/operators of Beechcraft Model G36 (with Garmin G1000 avionics installed) review the Garmin Service Bulletin 1132, Revision A at your earliest opportunity.

This Service Bulletin consists of new software versions for Garmin GDU 104X, GIA 63W, GDL 69A, GRS 77, GDC 74A, and GTS 820 products. This upgrade also resolves the GTS 8XX related issue described in Garmin Service Advisory 1103. After this Service Bulletin has been implemented, certain optional features/products may be installed per Garmin Service Bulletin 1019, Revision B.

A copy of Garmin Service Bulletin 1132, Revision A may be obtained from the Dealer Resource Center portion of the Garmin website www.garmin.com.

Note:

Hawker Beechcraft Corporation assumes no responsibility for providing revisions or changes to this or any supplier information.



SOFTWARE SERVICE BULLETIN

NO.: 1132 Revision A

TO: All Garmin Aviation Service Centers
DATE: October 27, 2011
SUBJECT: G1000 system upgrade for G1000 WAAS-equipped Hawker Beechcraft G36 Bonanza aircraft to System Software Version 0858.08 (only applicable to aircraft using System SW Version 0858.07).

PURPOSE

This system upgrade consists of new software versions for Garmin GDU 104X, GIA 63W, GDL 69A, GRS 77, GDC 74A, and GTS 820 products. This upgrade also resolves the GTS 8XX related issue described in Garmin Service Advisory 1103. After this Service Bulletin has been implemented, certain optional features/products may be installed per Garmin Service Bulletin 1019 Revision B.

DESCRIPTION

This Service Bulletin provides instructions for upgrading Garmin G1000 System Software to Version 0858.08 for Hawker Beechcraft G36 Bonanza aircraft equipped with Garmin STC #SA01595WI-D and System Software Version 0858.07.

PRODUCT AFFECTED

This service bulletin is only applicable to G1000 WAAS-equipped Hawker Beechcraft G36 Bonanza aircraft with G1000 System Software version 0858.07 that are equipped with Garmin STC #SA01595WI-D.

APPROVAL

This upgrade for G1000 WAAS-equipped Hawker Beechcraft G36 Bonanza aircraft having System Software Version 0858.07 is FAA-approved for installation in accordance with STC #SA01595WI-D with Master Drawing List revision 5 or later approved revision. Refer to the document STC SA01595WI-D.pdf, available for free download from the Dealer Resource Center portion of the Garmin website www.garmin.com.

© Copyright 2011
Garmin Ltd. or its subsidiaries
All Rights Reserved

Except as expressly provided herein, no part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this document and of any revision to this document onto a hard drive or other electronic storage medium to be viewed and to print one copy of this document or of any revision hereto, provided that such electronic or printed copy of this document or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this document or any revision hereto is strictly prohibited.